




REPLACEMENT - CARTE ELECTRONIQUE - DEFECTUEUSE
 REPLACEMENT OF DEFECTIVE - ELECTRONIC BOARD
 AUSTAUSCH FEHLERHAFT - ELEKTRONIK CARTE

1



2



XP5220../1P0 _ XP5220../1P1
 XP5240../1P0 _ XP5240../1P1


16/01/2012

MS-622279






1/2

REPLACEMENT - CARTE ELECTRONIQUE - DEFECTUEUSE
REPLACEMENT OF DEFECTIVE - ELECTRONIC BOARD
AUSTAUSCH FEHLERHAFTE - ELEKTRONIK CARTE

3



RO-CY9230
6,3 mm



XP5220../1P0 _ XP5220../1P1
 XP5240../1P0 _ XP5240../1P1

16/01/2012

MS-622279

2/2