


**REPLACEMENT CARTE ELECTRONIQUE DEFECTUEUSE  
REPLACEMENT DEFECTIVE ELECTRONIC BOARD  
AUSTAUSCH FEHLERHAFTE ELEKTRONISCHE KARTE**




SS-988181

*Remplacée par  
Replace by  
Ersetzt durch*



SS-193152



**1**



**2**



CT233 / ... / CT278


10/12/2009

MILANO - BRUNCH



1/2

REPLACEMENT CARTE ELECTRONIQUE DEFECTUEUSE  
 REPLACEMENT DEFECTIVE ELECTRONIC BOARD  
 AUSTAUSCH FEHLERHAFTE ELEKTRONISCHE KARTE

3



4



CT233 / ... / CT278

10/12/2009

MILANO - BRUNCH

2/2